cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · · · ·										
Intersection ID: 20552	Main Street: LUTOMMA_CR			Street:	SARDIS_RD	Location:	SW			
ADA ID: 9A3C3FDD9428	Ramp Tv	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				22.5	
					· · · ·					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	C. C. C. C. T. T. T. T. T. T. T. T. T. T. T. T. T.	Possible Solutions:		Compliance Description		Data Compliance			Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)		No	Ramp Slope (%)	10.4	
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)		No	Ramp XSlope (%)	3.0	
				N/A	Flare Type LT		N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A	
E P				N/A	Flare Traversable LT?		N/A	Flare Traversable RT?	N/A	
LUTOLILLA GR				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
ALL BREELE				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	1 196				X Walk 1 Direction	To E		X Walk 2 Direction	To N	
医明 說記 20				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	SARDIS RD				X Walk 1 Slope (%)	9.0		X Walk 2 Slope (%)	1.1	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	7.0	
Street 2 Name	LUTOMMA CR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	2.6	N/A	Clear Space?	N/A	
					Road X Slope (%)	7.5	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
		-			· 7 F -	N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	
							1.00		3004	

