

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

14.9

3.0

N/A

No

To N

N/A

2.5

0.4

N/A

N/A

N/A

N/A

N/A

Good

Hazard?

Cross Street: N/A Location: Intersection ID: 10021320 Main Street: BLAKENEY GREENS BV SW Initial Pass/Fail: Fail **Overall Compliance: No ADA ID: 9A8D4EAA0B17** Ramp Type: PerpDiag Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Flare Traversable RT?

Flare Type RT

Data

125.0

92.0

N/A

No

N/A

0.1

0.6

N/A N/A

To SE



N/A Street 1 Name Stop Condition-Street 2 None Street 2 Name **BLAKENEY GREENS BV** Stop Condition-Street 1 None

Possible Solution
Possible Solutions:
Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.
Surveyor Notes:
N/A
PROW/ADA: R304.2.2, R304.5.3

Cor	npliance Description
N/A	Ramp Length (in)
Yes	Ramp Width (in)
N/A	Flare Type LT
N/A	Flare Slope LT (%)
N/A	Flare Traversable LT?
N/A	Landing Length (in)
N/A	Landing Width (in)
N/A	Landing Slope (%)
N/A	Landing X Slope (%)
N/A	Landing Curb? (Y/N)
N/A	Shared Landing?
N/A	Gutter Ponding?
N/A	Gutter Lip Ht (in)
N/A	Painted X Walk1?
	X Walk 1 Direction
N/A	X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%)
N/A	Ramp inside XWalk1?
	Road Slope (%)
	Road X Slope (%)
N/A	Any Obstructions?

		Road Slope (%)	0.6	N/A	Clear Space?
		Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
\$ 3200.00		Obstruction Type			Storm Grate/Utility Type
			N/A		
				Yes	Surface Condition? (G/P)





Total Cost:

