

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

			•	<u> </u>						
Intersection ID: 5579	Main Street: FALLS_BRANCH_LN				Street:	GRAYS_CREEK_LN	Location:	w		
ADA ID: 9AB8990FEA60	Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		Data
		Remove & Ren	lace Entire Ram	0.	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	10.5
A ANNO	1 manual			-	No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	3.4
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1 1 AFTA				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
RAMAS PRO				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
RAILS FRANGELIN				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	LACE H	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	L Contraction	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
et all all all all all all all all all al	CA. Salar	10/2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	and the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	The c.				N/A	Shared Landing?	N/A		()	
PROW/ADA:					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		04.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	R304.5.3	004.5.1, K304.2.2,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				N/A	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GRAYS CREEK LN	1			11/4	X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	5.3 1.9		X Walk 2 X Slope (%)	N/A N/A
Stop Condition-Street 2	N/A				N/A	Ramp inside XWalk1?	1.9 N/A	N/A	Ramp inside XWalk2?	N/A
					IN/A					
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

