cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		· · · · · · · · · · · · · · · · · · ·	<u> </u>	<u> </u>					
Intersection ID: 10027660 Main Street: GREENWOOD_CLIFF				Cross Street: N/A				Location:	NW
ADA ID: 9AEE8B4488D7	DA ID: 9AEE8B4488D7 Ramp Type: Perp				Initial Pass/Fail: Pass Overall Compliance: No				0.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Date			Compliance Description		Data
	n Huk	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	5.6
	A BOTH			Yes	Ramp Width (in)	71.0	No	Ramp XSlope (%)	2.7
NAME OF CASE	C. S.			Yes	Flare Type L Curbed_NoW a	/alkSurface	N/A	Flare Type RT	N/A
	1914			Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	N/A
SI SIA PA				No	Landing Length (in)	46.5	Yes	DWS Provided?	Yes
	AL AL	Surveyor Notes:		Yes	Landing Width (in)	71.0	Yes	DWS Contrast?	Yes
E.	112 6 5	N/A		No	Landing Slope (%)	2.3	Yes	DWS Length (in)	24.0
	15 21			Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes
1. 6.00-				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	6.0
11 0 9	1 6 6	4		N/A	Shared Landing?	No			
		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.8
11 12 12	18112	Not Found, R304.5.3, R304.2.1,		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.7
No. 1.	11 5 1 1	R304.2.2-Perp, R304.3.2-Para,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
All Start Start	A long	R305.2			X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
All and and	TEN I I I I I I I I I I I I I I I I I I I	J		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GREENWOOD CLIFF				X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	Yes
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$	1850.00		Obstruction Type	1		Storm Grate/Utility Type	
						N/A			N/A
i de la constante de							1		

Yes Surface Condition? (G/P)

Good

