cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



No

Surface Condition? (G/P)

Poor

				-					
Intersection ID: 19036	Main Str	Main Street: RANDOLPH_RD			Cross Street: RANDSTONE_CT				E
ADA ID: 9B0F79A9D5A0	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				41.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A CONTRACTOR OF THE OWNER OF THE	STAR OF THE STAR	Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	np With	N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	16.8
			•	Yes	Ramp Width (in)	51.0	No	Ramp XSlope (%)	3.8
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
SI AND				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
E C				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<u>6</u>				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the terms of		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second se	Contraction 1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
No We Could be a second		Not Found, R304.2.2, R304.5.3,	3.	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		R302.7		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
the second se					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
		-		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RANDSTONE CT	-			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	1.0
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	1.1
Street 2 Name	RANDOLPH RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.4	N/A	Clear Space?	N/A
					Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

