

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18834 Main Street: GLENHAM_DR Cross Street: MILFORD_RD Location: SW

ADA ID: 9B1D48C39A05 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
MILFORD RD
Stop Condition-Street 1
StopSign
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.3

Total Cost: \$ 1600.00







