

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

N/A

N/A

Good

N/A

N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

				-	. /					
Intersection ID: 11348	Main Street: ASHLEY_RD				Street:	JOY_ST			Location:	SW
ADA ID: 9B272E3B42CD	Ramp Type: Combination1				Pass/Fa	ail: Fail Overa	lo Severity Score:	50		
Codes/Mit	igation Info	/Possible Solution				Field Meas	urements/C	ompo	onent Compliance	
		Possible Solutions:			Comp	liance Description			pliance Description	Data
	1 20 M	Remove & Replace Entir	e Rai	mp.	N/A	Ramp Length LT (in)	73.0	N/A	Ramp Length RT (in)	58.0
A State A State of State	at the				Yes	Ramp Width LT (in)	56.0	Yes	Ramp Width RT (in)	52.0
The second second	den.				Yes	Ramp Slope LT (%)	5.2	Yes	Ramp Slope RT (%)	5.0
A LA STORE A LANCE	26				Yes	Ramp XSlope LT (%)	2.0	No	Ramp XSlope RT (%)	3.3
	LOOA S.				N/A	Ramp Length (in)	55.0	No	Ramp Slope (%)	13.1
	MANA				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.3
ton all the second seco	2 · · · ·	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	29				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	The Alexand				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	- MAK				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	The	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	TOTON IT	R304.2.2, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	UTER!	,			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A A A A A A A A A A A A A A A A A A A	E N				N/A	Shared Landing?	N/A			
FLEAT STATES	to a				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	JOY ST				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 2 Name	N/A					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
						X Walk 1 X Slope (%)	6.4		X Walk 2 X Slope (%)	N/A
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	N/A		Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	1 Section 1					t		N/A	Any Obstruction?	N/A
		a state of the second			Dey was				Obstruction Type	





