

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

57.0

48.0

4.2

3.0

8.7

0.9

N/A

Intersection ID: N/A Main Street: SILVAIRE FARM RD Cross Street: SLEDGE RD Location: NE **Overall Compliance: No** ADA ID: 9B336017B22F Ramp Type: Combination1 Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

No

Nο

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

Flare Traversable RT?

Ramp XSlope RT (%)

Data

43.0

48.0

2.6

2.4

48.0

48.0

N/A

No

Flare Traversable LT?

Ramp XSlope LT (%)



StopSign Street 1 Name Stop Condition-Street 1 SILVAIRE FARM RD N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A	Ramp	Length LT (in
·	Yes	Ramp	Width LT (in)
	Yes	Ramp	Slope LT (%)
	No	Ramp	XSlope LT (%
	N/A	Ramp	Length (in)
	Yes	Ramp	Width (in)
Surveyor Notes:	N/A	Flare	Type LT
LT RP < 5%, RT RP < 5%	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L
	N/A	Landi	ng Length (in)
	N/A	Landi	ng Width (in)
PROW/ADA:	N/A	Landi	ng Slope (%)
Not Found, R304.2.2, R304.5.3	N/A	Landi	ng X Slope (%
	N/A	Landi	ng Curb? (Y/N
	N/A	Share	d Landing?
	N/A	Gutte	r Ponding?
	N/A	Gutte	r Lip Ht (in)
	N/A	Painte	ed X Walk1?
		X Wal	k 1 Direction
		X Wal	k 1 Width (in)
		X Wal	k 1 Slope (%)



Total Cost:



