

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

6.4

5.4

N/A

N/A

Good

11.0

Cross Street: MORTEZ AV Location: Intersection ID: N/A Main Street: STATESVILLE AV SE ADA ID: 9B95BCD806A4 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25 Ramp Type: Combination2

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

105.5

46.0

7.3

6.1

103.0

60.0

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)

N/A

N/A

N/A

N/A

Yes

No

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)



Street 1 Name StopSign **MORTEZ AV** Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description Remove & Replace Entire Ramp. N/A No Yes No N/A Yes Surveyor Notes: N/A N/A N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3 N/A N/A N/A N/A N/A N/A



Total Cost:



1600.00

Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	N/A		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
A STATE OF THE STA			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	_
	Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%)	Flare Traversable LT? Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? No X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? N/A Road Slope (%) N/A	Flare Traversable LT? Landing Length (in) Landing Width (in) N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) Road X Slope (%) N/A	Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Slope (%) X Walk 1 X Slope (%) X Walk 2 X Slope (%)

Yes

Surface Condition? (G/P)

Curb Slope (%)