

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18958 Main Street: GROVER\_RD Cross Street: OLD\_PINEVILLE\_RD Location: SE

ADA ID: 9BA5C1250EEB Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



| Street 1 Name           | GROVER RD |
|-------------------------|-----------|
| Stop Condition-Street 2 | StopSign  |
| Street 2 Name           | N/A       |
| Stop Condition-Street 1 | N/A       |

| ונ        | Possible Solution             |      | Fleid Measurements/Component Compilance |       |     |                             |      |  |
|-----------|-------------------------------|------|---|-------|-----|-----------------------------|------|--|
| ì         | Possible Solutions:           | Comp | Compliance Description Data             |       |     | Compliance Description      |      |  |
| Sept of   | Remove & Replace Entire Ramp. | N/A  | Ramp Length (in)                        | 110.0 | Yes | Ramp Slope (%)              | 5.7  |  |
| -         |                               | Yes  | Ramp Width (in)                         | 48.0  | No  | Ramp XSlope (%)             | 5.6  |  |
| A. C.     |                               | N/A  | Flare Type LT                           | N/A   | N/A | Flare Type RT               | N/A  |  |
| E         |                               | N/A  | Flare Slope LT (%)                      | N/A   | N/A | Flare Slope RT (%)          | N/A  |  |
| 5         |                               | N/A  | Flare Traversable LT?                   | N/A   | N/A | Flare Traversable RT?       | N/A  |  |
| c         |                               | N/A  | Landing Length (in)                     | N/A   | N/A | DWS Provided?               | N/A  |  |
| Section 1 | Surveyor Notes:               | N/A  | Landing Width (in)                      | N/A   | N/A | DWS Contrast?               | N/A  |  |
|           | N/A                           | N/A  | Landing Slope (%)                       | N/A   | N/A | DWS Length (in)             | N/A  |  |
|           |                               | N/A  | Landing X Slope (%)                     | N/A   | N/A | DWS Full Width?             | N/A  |  |
|           |                               | N/A  | Landing Curb? (Y/N)                     | N/A   | N/A | DWS Offset (in)             | N/A  |  |
| 1         |                               | N/A  | Shared Landing?                         | N/A   |     |                             |      |  |
| -         | PROW/ADA:                     | N/A  | Gutter Ponding?                         | N/A   | N/A | Gutter Slope (%)            | N/A  |  |
|           | R304.5.3                      | N/A  | Gutter Lip Ht (in)                      | N/A   | N/A | Gutter X Slope (%)          | N/A  |  |
| Ties.     |                               | N/A  | Painted X Walk1?                        | Yes   | N/A | Painted X Walk2?            | N/A  |  |
|           |                               |      | X Walk 1 Direction                      | To N  |     | X Walk 2 Direction          | N/A  |  |
|           |                               | N/A  | X Walk 1 Width (in)                     | 119.0 | N/A | X Walk 2 Width (in)         | N/A  |  |
|           |                               |      | X Walk 1 Slope (%)                      | 4.7   |     | X Walk 2 Slope (%)          | N/A  |  |
|           |                               |      | X Walk 1 X Slope (%)                    | 4.5   |     | X Walk 2 X Slope (%)        | N/A  |  |
|           |                               | N/A  | Ramp inside XWalk1?                     | Yes   | N/A | Ramp inside XWalk2?         | N/A  |  |
|           |                               |      | Road Slope (%)                          | N/A   | N/A | Clear Space?                | N/A  |  |
|           |                               |      | Road X Slope (%)                        | N/A   | N/A | Clear Space to XWalk (in)   | N/A  |  |
|           |                               | N/A  | Any Obstructions?                       | N/A   | N/A | Storm Grate/Utility Hazard? | N/A  |  |
|           | Total Cost: \$ 1850.          | .00  | Obstruction Type                        |       |     | Storm Grate/Utility Type    |      |  |
|           |                               |      |   | N/A   |     |                             | N/A  |  |
|           |                               |      |   |       | Yes | Surface Condition? (G/P)    | Good |  |
|           |                               |      |   |       |     |                             |      |  |





