cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47699	47699 Main Street: N_SHARON_AMITY_RD			Street:	NIGHT_HERON_LN	Location:	NE		
ADA ID: 9C38B0645957	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compli			liance Description	Data	
A LAND		Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	129.0	Yes	Ramp Slope (%)	5.4
		Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	45.0	No	Ramp XSlope (%)	5.1
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E S		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and the second s	1 102 800			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
G BARREN CONTRACTOR				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	1				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	NIGHT HERON LN	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	0.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.7		X Walk 2 X Slope (%)	2.4
Street 2 Name N SH	HARON AMITY RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.5	N/A	Clear Space?	N/A
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

