

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

Yes

6.8

0.1

N/A

N/A

N/A

Yes

Yes

24.0

Yes

19.0

84.5

3.0

3.9

0.6

6.3

Yes

N/A

No

N/A

9.5

Good

Intersection ID: 10597 Main Street: BELLE PLAINE DR Cross Street: BRIARGROVE DR Location: SW **Overall Compliance: No Severity Score:** 0 ADA ID: 9C635D6A67DD Ramp Type: Directional1 Initial Pass/Fail: Pass

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

Yes

No

Yes

N/A

N/A

N/A

Yes

Yes

Yes

Yes

No

No

Yes

Yes

N/A

Yes

Yes

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Storm Grate/Utility Hazard?

Gutter X Slope (%)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

108.5

60.0

5.8

1.4

N/A

N/A

N/A

60.0

60.0

0.3

1.7

N/A

No

No

0.0

No

To N

N/A

0.6

6.3

N/A

No

N/A No

Ramp Length (in)

Ramp Width (in)

Ramp Slope (%)

Flare Type LT

Ramp XSlope (%)

Flare Slope LT (%)

Flare Traversable LT?

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Gutter Ponding?** 

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Any Obstructions?

**Obstruction Type** 



**BELLE PLAINE DR** Street 1 Name Stop Condition-Street 1 None N/A Street 2 Name Stop Condition-Street 2 N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. Yes Yes Yes N/A N/A Surveyor Notes: N/A N/A Yes Yes Yes Yes PROW/ADA: N/A Not Found, R304.5.3, R305.2 N/A Yes Yes N/A





Total Cost:



N/A

Yes

1600.00