

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10019944	: 10019944 Main Street: ARDREY_KELL_RD			Street:	N/A	Location:	S		
ADA ID: 9C6E20218CE3	A ID: 9C6E20218CE3 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	E III / III	Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Entire Ram	n	N/A	Ramp Length (in)	80.0	No	Ramp Slope (%)	8.5
	Y I I		Υ.	Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	0.9
	- P			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
· A Barnetter	Beater			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	6			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	EX_KELLAND			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
- Color	ANE	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	the second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		2110 011001 ()	
T I		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 - A - A - A - A - A - A - A - A - A -	thinking a line	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	ALL STREET			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				11/4	X Walk 1 Direction	To N		X Walk 2 Direction	N/A
TT				N/A	X Walk 1 Width (in)		N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ARDREY KELL RD	l de la constante de		N/A	X Walk 1 Slope (%)	1.5	N/A	X Walk 2 Slope (%)	N/A
	None					0.2			N/A N/A
Stop Condition-Street 2 Street 2 Name	N/A			N/A	X Walk 1 X Slope (%)		N/A	X Walk 2 X Slope (%)	N/A N/A
				N/A	Ramp inside XWalk1?	N/A		Ramp inside XWalk2?	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

s Surface Condition? (G/P)

Good

