

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

1.8

2.8

N/A

N/A

N/A

N/A

4.3

Good

Intersection ID: 52449 Main Street: TRANQUIL\_OAK\_PL Cross Street: PAT\_GARRETT\_ST Location: SW

ADA ID: 9C6E357A42F2 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

N/A

Yes

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter X Slope (%)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Storm Grate/Utility Hazard?

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)



Street 1 Name	PAT GARRETT ST
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	Comp	oliance Description	Data
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	67.0
	Yes	Ramp Width (in)	66.0
	No	Ramp Slope (%)	14.2
	Yes	Ramp XSlope (%)	0.8
	N/A	Flare Type LT	N/A
	N/A	Flare Slope LT (%)	N/A
Surveyor Notes:	N/A	Flare Traversable LT?	N/A
N/A	N/A	Landing Length (in)	0.0
	N/A	Landing Width (in)	0.0
	N/A	Landing Slope (%)	0.0
	N/A	Landing X Slope (%)	0.0
PROW/ADA:	N/A	Landing Curb? (Y/N)	N/A
R304.2.2	N/A	Shared Landing?	N/A
	N/A	Gutter Ponding?	0.0
	N/A	Gutter Lip Ht (in)	2.0
	N/A	Painted X Walk1?	No
		X Walk 1 Direction	To N
		X Walk 1 Width (in)	N/A
		X Walk 1 Slope (%)	1.8
		X Walk 1 X Slope (%)	2.8
	N/A	Ramp inside XWalk1?	N/A
	N/A	Any Obstructions?	N/A

1600.00





Total Cost:



Obstruction Type