

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13936Main Street: S_KINGS_DRCross Street: CHARLOTTETOWNE_AVLocation:SEADA ID: 9C86E5E8D8CCRamp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name CHARLOTTETOWNE AV
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

| 513 | Possible Solutions: | <u>C</u> |
|----------|-------------------------------|----------|
| | Remove & Replace Entire Ramp. | N |
| | | Υ |
| 100 | | N |
| STATE OF | | N |
| 9 | | N |
| 1 | | N |
| ı | Surveyor Notes: | N |
| Mal | N/A | N |
| | | N |
| | | N |
| - | | N |
| 80 | PROW/ADA: | N |
| Sec. | Not Found, R304.2.2, R304.5.3 | N |
| The same | | N |
| | | N |
| | | N |
| | | |

| | 2002 | 100 |
|---|------|--|
| 1 | | OR SHEET NO. |
| | | CONTRACTOR OF THE PERSON |
| | | The party of the contract of t |



Total Cost:



1850.00

| Fleid Measurements/Component Compnance | | | | | | | | |
|--|-----------------------|-------|------------------------|-----------------------------|------|--|--|--|
| Compliance Description D | | Data | Compliance Description | | Data | | | |
| N/A | Ramp Length (in) | 60.0 | No | Ramp Slope (%) | 10.1 | | | |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 5.2 | | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | | |
| N/A | Shared Landing? | N/A | | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | | |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | | |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A | | | |
| | X Walk 1 Direction | To N | | X Walk 2 Direction | N/A | | | |
| N/A | X Walk 1 Width (in) | 110.0 | N/A | X Walk 2 Width (in) | N/A | | | |
| | X Walk 1 Slope (%) | 2.4 | | X Walk 2 Slope (%) | N/A | | | |
| | X Walk 1 X Slope (%) | 5.4 | | X Walk 2 X Slope (%) | N/A | | | |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A | | | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | | | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | | |
| | | N/A | | | N/A | | | |
| | | | Yes | Surface Condition? (G/P) | Good | | | |