cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8226 Main Street: CATHERINE_SIMMONS_AV Cross Street: CUSTER_ST								Location:	NW
ADA ID: 9CC7FAB5CED7 Ramp Type: PerpDiag			Initial P	itial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
August		Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	61.0	No	Ramp Slope (%)	9.4
				No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	0.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A starting		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
CATHERINE SIMMONS /	w g			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
and the second s		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CATHERINE SIMMONS AV				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	0.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	1.5
Street 2 Name	CUSTER ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.5	N/A	Clear Space?	N/A
					Road X Slope (%)	0.5	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
4							L		

Yes Surface Condition? (G/P)

Good

