cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16144	Main Str	Main Street: AUBURN_AV			Cross Street: GREYSTONE_RD				Ν	
ADA ID: 9CD09C262EA3	Ramp Ty	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall		l Compliance: No		o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	Sector Contraction of the sector of the sect	Possible Solutions:		Compliance Descr		iption Data Compli		liance Description	Data	
		Remove & Replace Curb Ramp V	Nith	N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	5.7	
		Two New Directional Ramps or Equivalent.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.5	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
eres .				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
1000				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second se	T J	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
A A A A A A A A A A A A A A A A A A A				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
J. PANZY				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	DOX RE TH	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	. And the				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
11 mail				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	GREYSTONE RD				X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	1.8	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	3.6	
Street 2 Name	AUBURN AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	2.6	N/A	Clear Space?	N/A	
					Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

