

# Access Compliance Report


## Public Rights-of-Way

### (Curb Ramps)

|                        |                               |                         |                        |
|------------------------|-------------------------------|-------------------------|------------------------|
| Intersection ID: 16634 | Main Street: OLD_PINEVILLE_RD | Cross Street: YANCEY_RD | Location: SW           |
| ADA ID: 9CDAB3ACAE39   | Ramp Type: PerpDiag           | Initial Pass/Fail: Pass | Overall Compliance: No |
|                        |                               | Severity Score: 0       |                        |

#### Codes/Mitigation Info/Possible Solution

#### Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.**

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.2.2-Perp, R304.3.2-Para**

Total Cost: \$ 3200.00

| Compliance | Description           | Data   | Compliance | Description                 | Data  |
|------------|-----------------------|--------|------------|-----------------------------|-------|
| N/A        | Ramp Length (in)      | 47.0   | Yes        | Ramp Slope (%)              | 5.3   |
| Yes        | Ramp Width (in)       | 48.0   | Yes        | Ramp XSlope (%)             | 0.7   |
| N/A        | Flare Type LT         | Sloped | N/A        | Flare Type RT               | N/A   |
| N/A        | Flare Slope LT (%)    | 3.1    | Yes        | Flare Slope RT (%)          | 1.4   |
| N/A        | Flare Traversable LT? | Yes    | N/A        | Flare Traversable RT?       | Yes   |
| Yes        | Landing Length (in)   | 73.0   | Yes        | DWS Provided?               | Yes   |
| Yes        | Landing Width (in)    | 48.0   | Yes        | DWS Contrast?               | Yes   |
| No         | Landing Slope (%)     | 2.8    | Yes        | DWS Length (in)             | 24.0  |
| Yes        | Landing X Slope (%)   | 0.8    | Yes        | DWS Full Width?             | Yes   |
| N/A        | Landing Curb? (Y/N)   | No     | Yes        | DWS Offset (in)             | 1.0   |
| N/A        | Shared Landing?       | No     |            |                             |       |
| Yes        | Gutter Ponding?       | No     | Yes        | Gutter Slope (%)            | 4.1   |
| Yes        | Gutter Lip Ht (in)    | 0.0    | Yes        | Gutter X Slope (%)          | 0.2   |
| N/A        | Painted X Walk1?      | No     | N/A        | Painted X Walk2?            | No    |
|            | X Walk 1 Direction    | To E   |            | X Walk 2 Direction          | To NE |
| N/A        | X Walk 1 Width (in)   | N/A    | N/A        | X Walk 2 Width (in)         | N/A   |
|            | X Walk 1 Slope (%)    | 1.7    |            | X Walk 2 Slope (%)          | 1.2   |
|            | X Walk 1 X Slope (%)  | 1.0    |            | X Walk 2 X Slope (%)        | 0.5   |
| N/A        | Ramp inside XWalk1?   | N/A    | N/A        | Ramp inside XWalk2?         | N/A   |
|            | Road Slope (%)        | 0.2    | N/A        | Clear Space?                | Yes   |
|            | Road X Slope (%)      | 1.6    | N/A        | Clear Space to XWalk (in)   | N/A   |
| Yes        | Any Obstructions?     | No     | Yes        | Storm Grate/Utility Hazard? | No    |
|            | Obstruction Type      |        |            | Storm Grate/Utility Type    |       |
|            |                       | N/A    |            |                             | N/A   |
|            |                       |        | Yes        | Surface Condition? (G/P)    | Good  |

Street 1 Name OLD PINEVILLE RD  
 Stop Condition-Street 2 None  
 Street 2 Name YANCEY RD  
 Stop Condition-Street 1 StopSign

