

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10041619 Main Street: WHITEHALL\_COMMONS\_CENTERosDIStreet: N/A Location: SW

ADA ID: 9D272AC3568A Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

## **Codes/Mitigation Info/Possible Solution**



**ENTRANCE** Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

11.0	Possible Solutions:						
ì	Remove & Replace Entire Ramp.						
ı							
ì							
-							
į							
,	Surveyor Notes:						
q	N/A						
4							
S A	PROW/ADA:						
	Not Found, R304.5.1, R304.2.2						
	110t 1 cana, 11004.5.1, 11004.2.2						
4							
1							

Total Cost:	\$	1850.00

Field Measurements/Component Compliance									
Comp	liance Description	Data	Comp	liance Description	Data				
N/A	Ramp Length (in)	76.5	No	Ramp Slope (%)	10.2				
No	Ramp Width (in)	47.0	Yes	Ramp XSlope (%)	2.0				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A				
N/A	Shared Landing?	N/A							
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A				
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A				
	X Walk 1 Direction	To E		X Walk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A				
	Road Slope (%)	N/A	N/A	Clear Space?	N/A				
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm Grate/Utility Type					
	• ·	N/A			N/A				
			Yes	Surface Condition? (G/P)	Good				
		'		- (211)					





