cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10140	Main Street: E_36TH_ST		Cross Street: N_ALEXANDER_ST					Location: E		
ADA ID: 9D877A43893F	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliand			nce: N	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:					Comp	Compliance Description		
1		Remove & Replace Curb Ramp W	/ith	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.9	
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.1	
23 3 8 11		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Puc a la la la				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
8				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
67	10 10 10 10 10 10 10 10 10 10 10 10 10 1			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	A DE CO	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
B Contraction of the second se		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
the second	8.6.8			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	6 T. 19			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
30/0000	a Contraction	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	and and	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	21			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No	
	21.201				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
a share to share				N/A	X Walk 1 Width (in)	102.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N ALEXANDER ST				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	5.8	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	8.1		X Walk 2 X Slope (%)	0.5	
Street 2 Name	E 36TH ST			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	4.7	N/A	Clear Space?	N/A	
					Road X Slope (%)	7.7	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

