



Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50941	Main Street: CANMORE_ST	Cross Street: CEDAR_WALK_LN	Location: SW
ADA ID: 9D9FFB6498BD	Ramp Type: NoRamp	Initial Pass/Fail: NoRamp	Overall Compliance: No
Severity Score: 100			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Provide Curb Ramp

Surveyor Notes:

N/A

PROW/ADA:

N/A

Compliance	Description	Data
------------	-------------	------

Total Cost: \$ 1500.00

