

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

3.2

3.3

N/A

N/A

N/A

N/A

6.1

Good

Intersection ID: 20874Main Street:STEELE_CREEK_RDCross Street:WESTINGHOUSE_COMMONS_DRLocation:NEADA ID: 9E3863092931Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

N/A N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset LT (in)

DWS Offset RT (in)

Gutter Slope (%)

Road Slope (%)

Clear Space?

Road X Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Storm Grate/Utility Hazard?

Gutter X Slope (%)

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

98.0

72.0

6.7

2.9 N/A

N/A

N/A

0.0

0.0

0.0

0.0

N/A

N/A

0.0

0.0

No

N/A

3.2

3.3

N/A

N/A

To SW



Street 1 Name	WESTINGHOUSE COMMONS DR
Stop Condition-Street	1 StopSign
Street 2 Name	N/A
Stop Condition-Street	2 N/A

1 Ossible Solution		i iciu ivicas
Possible Solutions:	Compli	ance Description
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)
·	Yes	Ramp Width (in)
	Yes	Ramp Slope (%)
	No	Ramp XSlope (%)
	N/A	Flare Type LT
	N/A	Flare Slope LT (%)
Surveyor Notes:	N/A	Flare Traversable LT?
N/A	N/A	Landing Length (in)
	N/A	Landing Width (in)
	N/A	Landing Slope (%)
	N/A	Landing X Slope (%)
PROW/ADA:	N/A	Landing Curb? (Y/N)
R304.5.3	N/A	Shared Landing?
	N/A	Gutter Ponding?
	N/A	Gutter Lip Ht (in)
	N/A	Painted X Walk1?
		X Walk 1 Direction
		X Walk 1 Width (in)
		X Walk 1 Slope (%)
		X Walk 1 X Slope (%)
	N/A	Ramp inside XWalk1?





Total Cost:



N/A

1600.00

Any Obstructions?

Obstruction Type