

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

Intersection ID: 4429	Main Street: AMARANTHUS_CT			Cross Street: PAINTED_FERN_CT					Location:	W
ADA ID: 9E3C87CC8FFB	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	37.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data	Data Compliance Description		
		Remove & Replace E	ntire Ramp		N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	20.0
	Va . 18				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.8
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	ALL AND				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Contraction of the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
THEP, FEWLOR	s an to	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
- Flillus	10				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
TOTAL BOARD	12				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	116-50				N/A	Shared Landing?	N/A			
A June 1		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	211 / Sec.	Not Found, R304.2.2,	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
0	11.200	, ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To N		X Walk 2 Direction	N/A
	ALC: NO.				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name F	PAINTED FERN CT					X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	6.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

