cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Internection ID: 42007	Main Street, ASULTON ODEEK D						Leastion	14/
Intersection ID: 43667	Main Street: ASHETON_CREEK_DR		Cross Street: AVEN_CREEK_CT				Location:	W
ADA ID: 9E534623914E	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: N			nce: N	o Severity Score:	35
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
	Remove & Replace Curb	Ramp Witl	א N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	6.5
	Two New Directional Rai		No	Ramp Width (in)	25.0	Yes	Ramp XSlope (%)	0.8
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
An althe all			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Ka H			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second se	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Le che all all all all all all all all all al			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	No.		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
1 · / · · · · · · · · · · · · · · · · ·	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	fine		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
	and the second sec		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ASHETON 0	CREEK DR			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	1.3
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	1.9
Street 2 Name AVEN	CREEK CT		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign			Road Slope (%)	2.5	N/A	Clear Space?	N/A
				Road X Slope (%)	0.4	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost:	\$ 3200	.00	Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

