

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

10.9

2.8

N/A

Good

Main Street: BRIARWICK LN Intersection ID: 10021759 Cross Street: N/A Location: NE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 9E81652FAE92 Ramp Type: Perp Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

64.0

58.5

N/A

2.0

No

To S

N/A

3.5

5.1

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



BRIARWICK LN Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A Ramp		p Length (in)
·	Yes	Ramp Width (in) Flare Type LT Flare Slope LT (%) Flare Traversable LT	
	N/A		
	N/A		
	N/A		
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Landing Slope (%)	
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.2.2	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	ılk 1 Width (in)
		X Wa	ılk 1 Slope (%)





Total Cost:



N/A

N/A

1850.00