cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3648	Main Street: ARMITAGE_DR		Cross	Cross Street: WHITE_CASCADE_DR				Location:	NW
ADA ID: 9E9DCDCFD4EC	Ramp Type: BlendTrans1		Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
WHITE CASCADE DR & C		Remove & Replace Curb Rar	nn With	N/A	Ramp Length (in)	39.5	Yes	BlendTrans Slope (%)	4.9
		Two New Directional Ramps		Yes	Ramp Width (in)	49.0	No	BlendTrans XSlope (%)	4.8
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
B				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		4		N/A	Shared Landing?	N/A		Dwo onset (iii)	10/4
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
					-				
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
State - The second state - The s				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
a selection of the second selection				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
	ARMIAGE DR				X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	0.9		Clear Space?	N/A
					Road X Slope (%)	4.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.9