

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13296 Main Str		eet: CENTRAL_AV	t: CENTRAL_AV			MORNINGSIDE_DR	Location:	NE		
ADA ID: 9EA166FBC	DA ID: 9EA166FBCE18 Ramp Type: Perp		Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	11 A - 4	Possible Solutions:			Compliance Description D			ta Compliance Description		Data
Contraction of	au au	Remove & Replace Entir	e Ram	D .	N/A	Ramp Length (in)	79.0	Yes	Ramp Slope (%)	7.3
				1	No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	2.2
A LAND					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	ELEP STEP				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	m lange and land				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
· ···································					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
· · · · · · · · · · · · · · · · · · ·		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
<u>e</u>	CENTRAL AV				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
					N/A	Shared Landing?	N/A			
- Children Children	<u>हिंह</u>	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R3	304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
a line and a line and a	and the	, , ,			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To W		X Walk 2 Direction	N/A
I DE MAL					N/A	X Walk 1 Width (in)	109.5	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MORNINGSIDE DR					X Walk 1 Slope (%)	2.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal					X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

