

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

5.4

2.8

N/A

N/A

N/A

N/A

Intersection ID: 3244 Main Street: CANTERBROOK DR **Cross Street: WORSLEY LN** Location: Ε Initial Pass/Fail: Fail **Overall Compliance: No** 10 **ADA ID: 9ECB62FDD1DF** Ramp Type: Perp **Severity Score:** 

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

Flare Traversable RT?

Data

96.0

43.5

N/A

N/A

N/A

N/A

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Flare Traversable LT?

Flare Type LT



Street 1 Name	CANTERBROOK DR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Compliance Description Possible Solutions: N/A Remove & Replace Entire Ramp. No N/A N/A N/A N/A Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.5.3

			HIN THE	
		-0 7		
	innum -			

Total Cost:



1850.00



