## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		· · · · · · · · · · · · · · · · · · ·		• /					
Intersection ID: 5713	Main Str	Main Street: RIDGE_ACRES_RD			TRAILING_ROCK_DR		Location:	w	
ADA ID: 9EE084E02AE2	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Pass Overall Compliance			o Severity Score:	10.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			ata Compliance Description		Data
		Remove & Replace Entire Ram	Ramp.	N/A	Ramp Length (in)	34.0	Yes	Ramp Slope (%)	6.3
	The State	Remove & Replace Gutter.		Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
		·		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	7.2		Flare Slope RT (%)	4.2
E.				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
	L. C.			No	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
Contraction of the		Surveyor Notes:		No	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
		N/A		No	Landing Slope (%)	N/A	Yes	DWS Length (in)	25.0
		N/A		No	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
- We				N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
		4		N/A	Shared Landing?	No			0.0
		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.1
The same	12 12 1		0.4	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.0
	and a large	Not Found, R304.5.3, R304.2 R304.2.2-Perp, R304.3.2-Par	•	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	3.0 N/A
	A Frank Mar	K304.2.2-Feip, K304.3.2-Fai	la	N/A	X Walk 1 Direction		N/A	X Walk 2 Direction	N/A N/A
					To E				
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	RIDGE ACRES RD				X Walk 1 Slope (%)	4.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	Yes
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost:	\$ 2600.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

