cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 21991 M	Main Street: WINGET_RD		Cross Street: WITHERS_MILL_DR			Location:	NW	
ADA ID: 9F48E7B473EA R	Ramp Type: PerpDiag		nitial Pass/Fail: Fail Overall Compliance: No			Severity Score:	25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
A AND A AND A A	Possible Solutions:					iance Description	Data	
	Remove & Replace Curb Ramp V	Vith N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	7.6	
	Two New Directional Ramps or	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.3	
	Equivalent.	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Alex .	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	the state of the s	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	the state of the s	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A		N/A	N/A	DWS Contrast?	N/A	
	NA	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
G. C.		N/A	• • • • •	N/A	N/A	DWS Offset (in)	N/A	
Contraction (1996)	and a second	N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.3	N/A	•	N/A	N/A	Gutter X Slope (%)	N/A	
		N/A	,	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To SW		X Walk 2 Direction	To SE	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name WING	ET RD		X Walk 1 Slope (%)	8.1		X Walk 2 Slope (%)	1.5	
Stop Condition-Street 2	None		X Walk 1 X Slope (%)	1.4		X Walk 2 X Slope (%)	7.2	
Street 2 Name WITHERS MI	ILL DR	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Sto	pSign		Road Slope (%)	8.2	N/A	Clear Space?	N/A	
-			Road X Slope (%)	6.7	N/A	Clear Space to XWalk (in)	N/A	
		N/A	• • • •		N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 3	200.00	Obstruction Type			Storm Grate/Utility Type		
			••	N/A			N/A	

Yes Surface Condition? (G/P)

Good

