


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 16329	Main Street: DAWNWOOD_DR	Cross Street: HELMDALE_AV	Location:	E
ADA ID: 9F4CDDA70B7B	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.					
	Surveyor Notes:		N/A					
	PROW/ADA:		Not Found, R304.2.2					
	Total Cost:		\$ 3200.00					
	Street 1 Name		DAWNWOOD DR					
	Stop Condition-Street 2		StopSign					
	Street 2 Name		HELMDALE AV					
	Stop Condition-Street 1		None					
			Compliance	Description	Data	Compliance	Description	Data
			N/A	Ramp Length (in)	33.0	No	Ramp Slope (%)	8.8
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.9
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	5.2		X Walk 2 Slope (%)	3.5
				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	6.2
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	0.4	N/A	Clear Space?	N/A
				Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
				Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good

Street 1 Name	DAWNWOOD DR
Stop Condition-Street 2	StopSign
Street 2 Name	HELMDALE AV
Stop Condition-Street 1	None

