

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·										
Intersection ID: 18579	Main Str	Cross Street: WATERLEAF_LN					Location:	NE		
ADA ID: 9F6454B2F0DA	Ramp Ty	Initial Pass/Fail: Fail Overall Compliance:				ce: N	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description			Data	Data Compliance Description			
		Remove & Replace Curb Ramp W	ith N	I/A	Ramp Length (in)	38.0	No	Ramp Slope (%)	9.4	
		Two New Directional Ramps or		'es	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.4	
		Equivalent.	Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:	N	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	N	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
LONGSPUR I			N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
the state of the s			N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	stall a comment		N	I/A	Shared Landing?	N/A				
	W. LAN	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	1 2	R304.2.2	Ν	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A 15		N	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	And Top of the				X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
and the second s			N	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	WATERLEAF LN				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	0.9	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	0.7	
Street 2 Name	LONGSPUR DR		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	0.0	N/A	Clear Space?	N/A	
					Road X Slope (%)	2.2	N/A	Clear Space to XWalk (in)	N/A	
			١	A/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

es Surface Condition? (G/P)

Good

