


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10033988		Main Street: PARK_RD		Cross Street: N/A		Location: SW			
ADA ID: 9F6C858EFE37		Ramp Type: Directional2		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 13.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
<div></div> <div>Possible Solutions:</div> <div>Remove & Replace Entire Ramp.</div> <div>Surveyor Notes:</div> <div>N/A</div> <div>PROW/ADA:</div> <div>R304.2.2, R304.5.3</div> <div>Street 1 NameENTRANCE</div> <div>Stop Condition-Street 1None</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div> <div>Total Cost:\$1800.00</div>				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length (in)	75.5	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
				No	Ramp Slope (%)	9.1	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	4.0			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
				N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	1.7
					X Walk 1 Direction	To NW		Road X Slope (%)	1.9
					X Walk 1 Width (in)	N/A		Clear Space?	N/A
					X Walk 1 Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
					X Walk 1 X Slope (%)	1.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
					Obstruction Type		Yes	Surface Condition? (G/P)	Good
							N/A	Curb Slope (%)	14.5

