


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 8606	Main Street: ISENHOUR_ST	Cross Street: JUSTICE_AV	Location:	SE
ADA ID: 9F74E3749BFA	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 10

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance										
	Possible Solutions:		<b>Compliance</b>			<b>Description</b>			<b>Data</b>				
	<b>Remove &amp; Replace Entire Ramp.</b>		<b>N/A</b>	Ramp Length (in)		<b>49.0</b>		<b>Yes</b>	Ramp Slope (%)		<b>5.4</b>		
			<b>No</b>	Ramp Width (in)		<b>47.0</b>		<b>Yes</b>	Ramp XSlope (%)		<b>4.7</b>		
			<b>N/A</b>	Flare Type LT		<b>N/A</b>		<b>N/A</b>	Flare Type RT		<b>N/A</b>		
			<b>N/A</b>	Flare Slope LT (%)		<b>N/A</b>		<b>N/A</b>	Flare Slope RT (%)		<b>N/A</b>		
			<b>N/A</b>	Flare Traversable LT?		<b>N/A</b>		<b>N/A</b>	Flare Traversable RT?		<b>N/A</b>		
			<b>N/A</b>	Landing Length (in)		<b>N/A</b>		<b>N/A</b>	DWS Provided?		<b>N/A</b>		
			<b>N/A</b>	Landing Width (in)		<b>N/A</b>		<b>N/A</b>	DWS Contrast?		<b>N/A</b>		
			<b>N/A</b>	Landing Slope (%)		<b>N/A</b>		<b>N/A</b>	DWS Length (in)		<b>N/A</b>		
			<b>N/A</b>	Landing X Slope (%)		<b>N/A</b>		<b>N/A</b>	DWS Full Width?		<b>N/A</b>		
Surveyor Notes:													
<b>N/A</b>													
PROW/ADA:													
<b>Not Found, R304.5.1</b>													
Street 1 Name		<b>JUSTICE AV</b>											
Stop Condition-Street 2		<b>None</b>											
Street 2 Name		<b>N/A</b>											
Stop Condition-Street 1		<b>N/A</b>											
Total Cost:		<b>\$ 1850.00</b>											

Street 1 Name	JUSTICE AV
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

