


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 7770	Main Street: E_ARROWHEAD_DR	Cross Street: N_TRYON_ST	Location:	SW
ADA ID: 9F9F61282964	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 20

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Yes	Ramp Length (in)	93.0
	Remove & Replace Gutter.		Yes	Ramp Width (in)	48.0
			N/A	Flare Type LT	Sloped
			N/A	Flare Slope LT (%)	9.3
			N/A	Flare Traversable LT?	No
			Yes	Landing Length (in)	72.0
			Yes	Landing Width (in)	48.5
			Yes	Landing Slope (%)	2.0
			Yes	Landing X Slope (%)	1.0
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R305.2, R302.7, R302.7.2, R304.5.4</p>			N/A	Flare Type RT	N/A
			N/A	Flare Slope RT (%)	5.2
			N/A	Flare Traversable RT?	No
			Yes	DWS Provided?	Yes
			Yes	DWS Contrast?	Yes
			Yes	DWS Length (in)	24.0
			Yes	DWS Full Width?	Yes
			N/A	DWS Offset (in)	2.5
			No	Shared Landing?	No
			No	Gutter Ponding?	Yes
<p>Total Cost:</p> <p>\$ 2600.00</p>			No	Gutter Lip Ht (in)	1.0
			N/A	Painted X Walk1?	Yes
				X Walk 1 Direction	To E
			N/A	X Walk 1 Width (in)	120.0
				X Walk 1 Slope (%)	1.1
				X Walk 1 X Slope (%)	0.2
			Yes	Ramp inside XWalk1?	Yes
				Road Slope (%)	N/A
				Road X Slope (%)	N/A
			Yes	Any Obstructions?	No
				Obstruction Type	
			N/A		N/A
			Yes	Surface Condition? (G/P)	Good

