




Access Compliance Report

Public Rights-of-Way

(Curb Ramps)



Intersection ID: N/A	Main Street: PROVIDENCE RD W	Cross Street: N/A	Location: NW
ADA ID: 9FA99E0E7771	Ramp Type: Para	Initial Pass/Fail: Fail	Overall Compliance: No Severity Score: 37.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Remove & Replace Entire Ramp.						
	Surveyor Notes:		N/A						
	PROW/ADA:		R304.3.2, R304.5.3						
	Street 1 Name		ENTRANCE						
	Stop Condition-Street 1		None						
	Street 2 Name		N/A						
	Stop Condition-Street 2		N/A						
	Total Cost:		\$ 1600.00						
				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length LT (in)	72.0	N/A	Ramp Length RT (in)	53.0
				Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	60.0
			Yes	Ramp Slope LT (%)	1.8	No	Ramp Slope RT (%)	12.8	
			Yes	Ramp XSlope LT (%)	1.6	No	Ramp XSlope RT (%)	6.5	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	59.5	N/A	X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A	
				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
				Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	
						Yes	Surface Condition? (G/P)	Good	
						N/A	Curb Slope (%)	8.4	

