

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23917 Main Street: BOSHAM LN **Cross Street: WHITWORTH_WY** Location: NE **Overall Compliance: No** ADA ID: 9FD0DF23D45D Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name **BOSHAM LN** Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	
Sun over Netec:	
Surveyor Notes:	
N/A	
PROW/ADA:	
Not Found, R304.5.1, R304.2.2	I

				N/A
Surveyor Notes:				N/A
N/A				N/A
				N/A
				N/A
				N/A
PROW/ADA:				N/A
Not Found,	R304.5.1, R304.2	2.2		N/A
				N/A
				N/A
				N/A
Total Cost:	\$		1850.00	N/A
	•			

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	44.0	No	Ramp	Slope (%)	9.0
No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	2.0
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	7.0		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.7		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





