


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 11518	Main Street: VERONICA_DR	Cross Street: WHISPERFIELD_LN	Location: S
ADA ID: 9FF40255AC14	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 8.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance		
	Possible Solutions:		Compliance	Description	Data
	Remove & Replace Entire Ramp.		Yes	Ramp Slope (%)	6.3
			No	Ramp Width (in)	0.4
			N/A	Flare Type LT	N/A
			N/A	Flare Slope LT (%)	N/A
			N/A	Flare Traversable LT?	N/A
			N/A	Flare Traversable RT?	N/A
			N/A	DWS Provided?	N/A
			N/A	DWS Contrast?	N/A
			N/A	DWS Length (in)	N/A
			N/A	DWS Full Width?	N/A
			N/A	DWS Offset (in)	N/A
			N/A	Gutter Ponding?	N/A
			N/A	Gutter X Slope (%)	N/A
			No	Painted X Walk1?	N/A
			To NW	X Walk 2 Direction	N/A
			N/A	X Walk 2 Width (in)	N/A
			9.6	X Walk 2 Slope (%)	N/A
			3.7	X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk2?	N/A
			N/A	Clear Space?	N/A
			N/A	Clear Space to XWalk (in)	N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Storm Grate/Utility Type	N/A
			N/A	Surface Condition? (G/P)	Good
Surveyor Notes:					
N/A					
PROW/ADA:					
Not Found, R304.5.1					
Total Cost:		\$ 1850.00			

Street 1 Name	WHISPERFIELD LN
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

