

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11418 Main Street: AIRLIE_ST Cross Street: HILLIARD_DR Location: N

ADA ID: A023E6E56EBF Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name

Stop Condition-Street 1

None
Street 2 Name

N/A

Stop Condition-Street 2

N/A

<u> </u>	i ossible solution
Sec. of	Possible Solutions:
A	Remove & Replace Entire Ramp.
	Surveyor Notes:
	N/A
10	PROW/ADA:
Sales Control of the last of t	R304.2.2





Total Cost:



1600.00

Field Measurements/Component Compliance								
Compliance Description		Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	79.5	N/A	Grade	e Break?	N/A		
Yes	Ramp Width (in)	55.0	N/A	Grade	e Break Slope (%)	0.0		
No	Ramp Slope (%)	9.5	N/A	Grade	e Break XSlope (%)	0.0		
Yes	Ramp XSlope (%)	1.8						
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	0.0		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	0.0	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	0.0	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	0.0	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	0.0	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset LT (in)	N/A		
N/A	Shared Landing?	N/A	N/A	DWS	Offset RT (in)	N/A		
N/A	Gutter Ponding?	0.0	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No		Road	Slope (%)	3.6		
	X Walk 1 Direction	To SE		Road	X Slope (%)	3.8		
	X Walk 1 Width (in)	N/A		Clear	Space?	N/A		
	X Walk 1 Slope (%)	3.6	N/A	Clear	Space to XWalk (in)	N/A		
	X Walk 1 X Slope (%)	3.8	N/A	Storm	Grate/Utility Hazard?	N/A		
N/A	Ramp inside XWalk1?	N/A		Storm	Grate/Utility Type			
N/A	Any Obstructions?	N/A				N/A		
	Obstruction Type		Yes	Surfa	ce Condition? (G/P)	Good		
		N/A	N/A	Curb	Slope (%)	17.5		