


Intersection ID: 9993436	Main Street: PLAZA_END_TC	Cross Street: MECKLENBURG_AV	Location:	NW
ADA ID: A054B0E9D4F0	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



### Possible Solutions:

### Remove & Replace Entire Ramp.

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.2.2**

Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data			
<b>Remove &amp; Replace Entire Ramp.</b>			N/A	Ramp Length (in)	49.5	No	Ramp Slope (%)	11.0			
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.9			
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
			N/A	Shared Landing?	N/A						
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A			
			N/A	Gutter Lip Ht (in)	3.0	N/A	Gutter X Slope (%)	N/A			
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A			
Surveyor Notes: <b>N/A</b>				X Walk 1 Direction	To E		X Walk 2 Direction	N/A			
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A			
				X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A			
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
				Road Slope (%)	N/A	N/A	Clear Space?	N/A			
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A			
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
			Total Cost: \$ 1850.00				Obstruction Type			Storm Grate/Utility Type	
								N/A			N/A
								Yes	Surface Condition? (G/P)	Good	

Total Cost: \$ 1850.00

