

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 43078Main Street:WESLEY_HEIGHTS_WYCross Street:WESTBROOK_DRLocation:NADA ID: A08A4E094571Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:35

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

WESLEY HEIGHTS WY
None
WESTBROOK DR
StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

| rield Measurements/Component Compilance | | | | | |
|---|-----------------------|------|------------------------|-----------------------------|------|
| Compliance Description | | Data | Compliance Description | | Data |
| N/A | Ramp Length (in) | 48.0 | Yes | Ramp Slope (%) | 5.0 |
| No | Ramp Width (in) | 27.0 | Yes | Ramp XSlope (%) | 1.1 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | То Е |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 3.4 | | X Walk 2 Slope (%) | 4.0 |
| | X Walk 1 X Slope (%) | 4.7 | | X Walk 2 X Slope (%) | 3.9 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.5 | N/A | Clear Space? | N/A |
| | Road X Slope (%) | 7.5 | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |

Yes

Surface Condition? (G/P)

Good





