

Access Compliance Report


Public Rights-of-Way

(Curb Ramps)

| | | | |
|-----------------------|---------------------------|-----------------------------|------------------------|
| Intersection ID: 2710 | Main Street: FAIRVISTA_DR | Cross Street: QUEENSBURY_CT | Location: NW |
| ADA ID: A11CF6698D4B | Ramp Type: PerpDiag | Initial Pass/Fail: Pass | Overall Compliance: No |
| | | Severity Score: 10 | |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2-Perp, R304.3.2-Para, R305

Total Cost: \$ 3200.00

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|--------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 33.5 | Yes | Ramp Slope (%) | 7.6 |
| Yes | Ramp Width (in) | 51.0 | Yes | Ramp XSlope (%) | 0.8 |
| N/A | Flare Type LT | Sloped | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | 2.2 | Yes | Flare Slope RT (%) | 1.2 |
| N/A | Flare Traversable LT? | Yes | N/A | Flare Traversable RT? | Yes |
| Yes | Landing Length (in) | 55.0 | No | DWS Provided? | No |
| Yes | Landing Width (in) | 59.0 | N/A | DWS Contrast? | No |
| No | Landing Slope (%) | 4.4 | N/A | DWS Length (in) | N/A |
| Yes | Landing X Slope (%) | 1.0 | N/A | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | No | | | |
| Yes | Gutter Ponding? | No | Yes | Gutter Slope (%) | 0.1 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.1 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | To E |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 0.5 | | X Walk 2 Slope (%) | 2.9 |
| | X Walk 1 X Slope (%) | 1.0 | | X Walk 2 X Slope (%) | 1.7 |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | 0.8 | N/A | Clear Space? | Yes |
| | Road X Slope (%) | 1.5 | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | Yes | | Surface Condition? (G/P) | Good |

