


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17770		Main Street: LORENE_AV		Cross Street: ROSWELL_AV		Location: SE							
ADA ID: A16300922872		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance									
				Possible Solutions:		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A		Ramp Length (in)		53.5			
Surveyor Notes:				N/A		Yes		Ramp Width (in)		59.5			
						Yes		Ramp Slope (%)		4.5			
PROW/ADA:				R304.5.3		No		Ramp XSlope (%)		5.6			
						N/A		Flare Type LT		N/A			
						N/A		Flare Slope LT (%)		N/A			
						N/A		Flare Traversable LT?		N/A			
						N/A		Landing Length (in)		0.0			
						N/A		Landing Width (in)		0.0			
						N/A		Landing Slope (%)		0.0			
						N/A		Landing X Slope (%)		0.0			
						N/A		Landing Curb? (Y/N)		N/A			
						N/A		Shared Landing?		N/A			
						N/A		Gutter Ponding?		0.0			
						N/A		Gutter Lip Ht (in)		0.0			
						N/A		Painted X Walk1?		No			
								X Walk 1 Direction		To N			
								X Walk 1 Width (in)		N/A			
								X Walk 1 Slope (%)		1.1			
								X Walk 1 X Slope (%)		1.4			
						N/A		Ramp inside XWalk1?		N/A			
						N/A		Any Obstructions?		N/A			
								Obstruction Type		Yes			
								Surface Condition? (G/P)		Good			
								Curb Slope (%)		N/A			
										10.3			
Street 1 Name				LORENE AV									
Stop Condition-Street 1				StopSign									
Street 2 Name				N/A									
Stop Condition-Street 2				N/A									
Total Cost:				\$		1600.00							

