cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 31713	rsection ID: 31713 Main Street: WEEPING_FIG_LN Cross Street: ALDER_CT							Location:	NW	
ADA ID: A171318B1005 Ramp Type: PerpDiag			Initial Pas	s/rall			18.75			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:	Compliance Description		Data Compliance Description		Data			
		Remove & Replace Curb Ramp W	/ith N	Α	Ramp Length (in)	47.5	Yes	Ramp Slope (%)	5.9	
		Two New Directional Ramps or	N	D	Ramp Width (in)	32.5	No	Ramp XSlope (%)	3.8	
		Equivalent.	N	Α	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N	A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
ALDER OT		Surveyor Notes:	N	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A	N	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N	A	Shared Landing?	N/A				
		PROW/ADA:	N	A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Martin Carlos	Not Found, R304.5.1, R304.5.3	N	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
	WY N				X Walk 1 Direction	To S		X Walk 2 Direction	To E	
			N	A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	ALDER CT	-			X Walk 1 Slope (%)	4.7		X Walk 2 Slope (%)	9.1	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.3		X Walk 2 X Slope (%)	2.0	
Street 2 Name	WEEPING FIG LN		N	A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	3.8	N/A	Clear Space?	N/A	
					Road X Slope (%)	4.8	N/A	Clear Space to XWalk (in)	N/A	
			N		Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type		
1						N/A			N/A	
4							I			

Yes Surface Condition? (G/P)

Good

