

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

45.0

65.0

0.2

1.0

2.9

2.1

N/A

Main Street: PROVIDENCE RD Cross Street: PROVIDENCE COUNTRY CLUB DR Intersection ID: 27788 Location: NE 35 **ADA ID: A17DE8BB2213** Ramp Type: Combination1 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Flare Traversable RT?

Ramp XSlope RT (%)

Data

40.5

60.0

13.6

0.4

69.5

44.5

N/A

Yes

To S

Flare Traversable LT?

Ramp XSlope LT (%)



Street 1 Name Signal Stop Condition-StreePROVIDENCE COUNTRY CLUB DR N/A Street 2 Name Stop Condition-Street 2 N/A

Possible Solutions:	Compl	iance	Description
Remove & Replace Entire Ramp.	N/A	Ram	c Length LT (in)
	Yes	Ram	Width LT (in)
	No	Ramp Slope LT (%)	
	Yes	Ramp XSlope LT (%	
	N/A	Ramp Length (in)	
	No	Ram	o Width (in)
Surveyor Notes:	N/A	Flare	Type LT
RT RP < 5%	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable LT
	N/A	Land	ing Length (in)
	N/A	Land	ing Width (in)
PROW/ADA:	N/A	Land	ing Slope (%)
Not Found, R304.5.1, R304.3.2	N/A	Land	ing X Slope (%)
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
	N/A	Gutte	er Ponding?
	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
		X Wa	ılk 1 Width (in)
		X Wa	ılk 1 Slope (%)
		V \//c	Jk 1 V Slope (0/

\$



Total Cost:



		X Walk 1 Width (in)	112.5		X Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A	
1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
		Road Slope (%)	N/A		Clear Space?	N/A	
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstruction?	N/A		
				Obstruction Type			
					N/A		
			N/A	Storm Grate/Utility Hazard?	N/A		
	ad Committee of the Com				Storm Grate/Utility Type	1471	
						N/A	
1				Yes	Surface Condition? (G/P)	Good	
					Curb Slope (%)	23.2	

