


Access Compliance Report Public Rights-of-Way (Curb Ramps)

Intersection ID: 2878	Main Street: BROKEN_PINE_LN	Cross Street: LONG_FOREST_DR	Location: SW
ADA ID: A1D78D4415AE	Ramp Type: NoRamp	Initial Pass/Fail: NoRamp	Overall Compliance: No
		Severity Score: 100	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

Provide Curb Ramp Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

N/A

Compliance	Description	Data
------------	-------------	------

Total Cost: \$ 1500.00

