

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28642 Main Street: PADSTOW CT Cross Street: STEWARTS CROSSING DR Location: SW **Severity Score:** ADA ID: A23A5F14C1FB Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** 16.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



STEWARTS CROSSING DR Street 1 Name Stop Condition-Street 2 None **PADSTOW CT** Street 2 Name Stop Condition-Street 1 StopSign

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.3, R302.7

Total Cost: 3200.00 Compliance Description Data Compliance Description Data Yes N/A Ramp Length (in) 39.5 Ramp Slope (%) 6.9 No Ramp XSlope (%) Yes Ramp Width (in) 48.0 4.0 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A **DWS Provided?** N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To E X Walk 2 Direction To N N/A N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.5 X Walk 2 Slope (%) 2.0 X Walk 1 X Slope (%) 2.4 X Walk 2 X Slope (%) 3.1 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 1.6 N/A Clear Space? N/A N/A Road X Slope (%) 0.2 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A

No

Surface Condition? (G/P)

Poor





