

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

7.9

3.0

N/A

Good

Intersection ID: 54465 Main Street: RUPELL DR **Cross Street: COLLINGHAM DR** Location: SW ADA ID: A2929B895DB2 **Overall Compliance: No** Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 1.25

## **Codes/Mitigation Info/Possible Solution**

## Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

105.0

48.0

N/A

1.0

No

To SE

N/A

3.6

1.5

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

**Obstruction Type** 

Flare Traversable LT?



Street 1 Name	RUPELL DR
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:	Compl	iance	Description
Remove & Replace Entire Ramp.	N/A	Ram	p Length (in)
·	Yes	Ram	p Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Shar	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	ılk 1 Width (in)
		X Wa	ılk 1 Slope (%)
		X Wa	ılk 1 X Slope (%
	N/A	Ram	p inside XWalk
		Road	Slope (%)

Total Cost:



N/A

1850.00

