

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3648 Main Street: ARMITAGE_DR Cross Street: WHITE_CASCADE_DR Location: NE

ADA ID: A2A1FC174768 Ramp Type: Directional1 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 2.5

ADA ID: A2A1FC174768 Ramp Type: Directional1			Initial	Pass/Fa	ail: Pass Overa	II Compliar	ce: N	o Severity Score:	2.5			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Comp	liance Description	Data	Compliance Description		Data		
]	CASCADE DR	Remove & Replace Entir	re Ramp.		N/A	Ramp Length (in)	36.0	Yes	Grade Break?	Yes		
					Yes	Ramp Width (in)	48.0	No	Grade Break Slope (%)	6.2		
					Yes	Ramp Slope (%)	3.0	No	Grade Break XSlope (%)	3.4		
					Yes	Ramp XSlope (%)	1.2					
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
		Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
<u>&</u>		N/A			No	Landing Length (in)	47.0	Yes	DWS Provided?	Yes		
Pulling of					Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes		
<u></u>					No	Landing Slope (%)	4.3	Yes	DWS Length (in)	25.0		
					Yes	Landing X Slope (%)	0.6	No	DWS Full Width?	No		
		PROW/ADA:			N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset LT (in)	50.5		
	Not Found, R304.2.1, R304.2.2-Pe			N/A	Shared Landing?	No	No	DWS Offset RT (in)	6.0			
/	R304.3.2-Para, R304.5.3, R305.1.4, R305.2		.1.4,	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.0			
I				Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.5			
				N/A	Painted X Walk1?	No		Road Slope (%)	3.5			
Street 1 Name	ARMITAGE DR					X Walk 1 Direction	To W		Road X Slope (%)	2.8		
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	Yes		
Street 2 Name	N/A					X Walk 1 Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A		
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	2.8	Yes	Storm Grate/Utility Hazard?	No		
					N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type			
					Yes	Any Obstructions?	No			N/A		
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good		
							N/A	No	Curb Slope (%)	17.3		





