

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9953 Main Street: TRIANGLE_DR Cross Street: TUCKASEEGEE_RD Location: S ADA ID: A2AACBC8B626 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



TRIANGLE DR Street 1 Name Stop Condition-Street 2 None Street 2 Name N/A Stop Condition-Street 1 N/A

	Possible Solutions:
of Dalland	Remove & Replace Entire Ramp.
9	
	Surveyor Notes:
	N/A
í	N/A
į	
	PROW/ADA:
Carles and	Not Found, R304.5.1, R304.2.2
1	
ı	



Total Cost:



1850.00

Field Measurements/Component Compliance								
Comp	Compliance Description		Compl	iance	Description	Data		
N/A	Ramp Length (in)	47.0	No	Ramp	Slope (%)	9.4		
No	Ramp Width (in)	42.0	Yes	Ramp	XSlope (%)	2.3		
N/A	N/A Flare Type LT		N/A	N/A Flare Type RT		N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.7		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.7		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		
	(b .							

